



DI

Value

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Applicant: Takehito Ito et al)
)
Serial No.: 10/619,350)
) Now U.S. Patent No. 6,962,639
Filed: July 4, 2003)
) Issued: November 8, 2005
For: Power Transmission Belt and)
a Method of Forming a Power)
Transmission Belt)
)
Examiner: S. Yao)

SECOND REQUEST FOR CERTIFICATE OF CORRECTION

Certificate of Correction Branch
Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313

Certificate
OCT 02 2008
of Correction

Sir:

On August 25, 2008, a Request for Certificate of Correction was submitted. The Request was denied in a mailing from the Patent Office on September 16, 2008.

As a basis for denial, it is indicated that column 11, line 54, is printed in accordance with the paperwork as passed to issue by the Examiner. However, in a Supplemental Notice of Allowability, the Examiner indicates that the subject amendment is made by Examiner's Amendment. The Examiner inadvertently identifies claim 20 as opposed to claim 2. However, claim 20 does not have 18 lines and it is thus clear that this is a typographical error on the Examiner's part.

37 CFR 1.8
CERTIFICATE OF MAILING

I hereby certify that this correspondence is being deposited with the U.S. Postal Service as first class mail in an envelope addressed to: Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450, on

9/25/08


Linda Bowen

It is requested that a Certificate of Correction be issued embodying the enclosed corrections.

Respectfully submitted,

By



John S. Mortimer, Reg. No. 30,407

Sept 25, 2008

WOOD, PHILLIPS, KATZ, CLARK & MORTIMER
Citicorp Center, Suite 3800
500 West Madison Street
Chicago, Illinois 60661-2562
312/876-1800

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO.: 6,962,639

Page 1 of 1

APPLICATION NO.: 10/619,350

ISSUE DATE: November 8, 2005

INVENTOR(S) Takehito Ito, Toshiaki Aragane, Koji Kitahama and Syunichi Imahigashi

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 11, line 54 should read as follows:

"pad is at a side surface on the cog crest and b) a free end of"

MAILING ADDRESS OF SENDER: (Please do not use customer number below):

Wood, Phillips, Katz, Clark & Mortimer
Citigroup Center, Suite 3800
500 West Madison Street
Chicago, Illinois 60661-2562
(312) 876-1800 (phone)

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Till will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: ATTENTION CERTIFICATE OF CORRECTIONS BRANCH, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.